

Eclipse 500 Engine Tail Cone Repair

Fiber Art Inc., Applied Aerodynamics Inc. and ESN/Brigadoon Aircraft Maintenance, LLC work to keep Eclipse Aircraft Flying.

Fiber Art Inc. of Cibolo, Texas and Applied Aerodynamics Inc., located in Dallas, Texas have signed a mutual agreement to support composite repair of Eclipse aircraft components. Working together, both companies have successfully delivered their first FAA approved repair on an Eclipse 500 engine tail cone for a client whose aircraft was grounded for lack of availability of a replacement part.

Mike Goldman, Executive VP of Business Development for Fiber Art Inc. and Dale Gable, General Manager for Applied Aerodynamics Inc., worked diligently with Cary Winter, Executive Vice President of Brigadoon Aircraft Maintenance, LLC to acquire the necessary material information utilized in the tail pipe to develop a repair that allowed the client's aircraft to get back in the air.

Fiber Art Inc. will be handling the sales, logistics and customer support of the Eclipse components and coordinating the repair requirements necessary with Applied Aerodynamics Inc.

Applied Aerodynamics Inc. is a major supplier of manufactured, repaired and/or overhauled radomes as well as bonded and sheet metal airframe related structures. Their extensive process capabilities in conjunction with their dedicated technicians and engineering staff allow them to support the needs of the Aerospace Industry throughout the World (www.aerodyn.com).

Fiber Art Inc. is an Industry provider that specializes in the design, engineering, repair and fabrication of custom interior/exterior composite components for OEM's, Completion Centers and Military Contractors (www.fiberartinc.com).

ESN/Brigadoon Aircraft Maintenance, LLC maintains the largest fleet of Eclipse aircraft and is a member of the Eclipse Service Network™ (www.brigadoonmaintenance.com).

Both Companies are excited to be able to provide composite repair services that will assist in keeping Eclipse Owners flying.

Customers and/or Eclipse Owners seeking additional information or quote for repair can e-mail sales@fiberartinc.com or contact Bernie Head (Director of Sales/Marketing) at 817-503-7098.